

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
<b>Site No. 55 Memorial Hall</b>								
<b>Basement</b>								
Theater Storage Rooms (Former Radio Station Mechanical Room)	Pipe Insulation		TSI	Yes	MNO	MNO	5, 8	Materials located above the ceiling.
	Pipe Fitting Insulation		TSI	Yes	MNO	MNO	5, 8	
	Duct Skim Coat		TSI	Yes	MNO	MNO	5, 8	
Wardrobe storage (Former Band Room)	9" Floor Tile, black and gold	500 SF	Misc.	NF	Good	NF	5, 8	Material confirmed ACBM by testing performed by GZA in 2024. Some materials have been covered over with carpet.
Room Adjacent to Women's Dressing Room	12" Floor Tile	360 SF	Misc.	No	Good	NF	5	Salmon colored, adjacent to 9" tile locations, assumed ACBM.
Women's Dressing Room	9" Floor Tile, black and gold	200 SF	Misc.	NF	Good	NF	5	Confirmed ACBM 2024 by sampling performed by GZA
Theater Storage (013)	Pipe Insulation	4 LF	TSI	Yes	Good	5	5	Material located above the ductwork/closet area
Mechanical (012)	Duct Expansion Cloth	6 SF	Misc.	No	Damaged	6	4	
Hall and Foyer outside restrooms, entry to ladies room	9" Floor Tile, black and gold	580 SF	Misc.	NF	Good	NF	5	Confirmed ACBM 2024 by sampling performed by GZA
Storage Closet	9" Floor Tile, black and gold	40 SF	Misc.	NF	MNO	MNO	5	No access.
Storage Closet (002)	9" Floor Tile, black and gold	80 SF	Misc.	NF	Good	NF	5	
<b>First Floor</b>								
Stage	Fire Curtain	1 Curtain	Misc.	Yes	Good		7	SPS has provided manufacturer documentation that asbestos was not used in the product.
Stairwell Hall	9" Floor Tile, black and gold	300 SF	Misc.	NF	MNO	MNO	5, 8	Materials have been covered over with carpet.

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site No. 55 Memorial Hall								
First floor, continued								
Balcony ceiling, Control room	Plaster	120 SF	Surfacing	Yes	Damaged	2	2	Limited removal in 2022, (6 SF), by Advanced Building Systems
Auditorium	9" Floor Tile, brown	4,100 SF	Misc.	NF	Damaged	NF	3	Materials observed to have some chipped, dented floor tiles present. Two floor tiles in front row broken with mastic exposed. Penetrations observed in floor at vertical conduit for new fire alarms.
Second Floor								
North Stairwell and lobby	9" Floor Tile, black and gold	540 SF	Misc.	NF	Good	NF	5	
Auditorium Ceiling	Troweled-On Surfacing Material	4,800 SF	Surfacing	Yes	Good	5	5	
Auditorium and Balcony Walls	Troweled-On Surfacing Material	400 SF	Surfacing	Yes	Good	5	5	
Auditorium Balcony	9" Floor Tile, black and gold	2,100 SF	Misc.	NF	Damaged	NF	3	Brown. Material was observed to have some chipped and missing floor tiles present.
Projector Room	Light (fixture) Wire	2 LF	Misc.	Yes	Good	5	5,6	Assumed ACBM
Attic								
Attic	Duct Expansion Cloth	40 SF	Misc.	NF	Good	5	5, 6	Assumed ACBM
Attic	Blown-in insulation	5,000 SF	TSA	Yes	Damaged	2	5, 6	Assumed ACBM
Throughout	Other suspect materials are present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any						6	See further discussion in report. Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
<b>Site No. 55 Memorial Hall</b>								
<b>Category:</b> MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
<b>Assessment Codes</b> based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
<b>Response Codes:</b> 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4. Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

### SPS 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 013 Music and Dance - 21 and 23 Hacylon Drive								
Music								
Exterior: West side Music building	Corrugated cementitious panel siding	800 SF	Misc.	No	Good		7	Exterior siding material excluded from AHERA regulations.
Dance								
Exterior: North side Dance building	Corrugated cementitious panel siding	1,500 SF	Misc.	No	Good		7	Exterior siding material excluded from AHERA regulations.
Throughout	Other suspect materials are present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation of demolition work.					6	See further discussion in report. Possible inaccessible ACBM also.	
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACBM; 2. Damaged friable surfacing ACBM; 3. Significantly damaged friable surfacing ACBM; 4. Damaged or significantly damaged friable miscellaneous ACBM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACBM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference the report, code description sheet, and the school management plan for discussion on assessment codes								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4. Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
<b>Alumni Hall-7 Rectory Road</b>								
<b>First Floor</b>								
107/108 Office	Floor Tile	486 SF	Misc.	NF	MNO	MNO	5, 8	Material has been covered over with carpeting.
100/119/120 Business Office	Floor Tile	486 SF	Misc.	NF	MNO	MNO	5, 8	
100 and 120 Business Offices	Fixed ceiling tile glue daubs	800 SF	Misc.	NF	MNO	MNO	7	Confirmed non-ACBM in 2023 testing by RPF
110/111 HR Office	9" Floor Tile	405 SF	Misc.	NF	MNO	MNO	7	Confirmed non-ACBM in 2023 testing by RPF
Staircase 115-315 from porch	12" Floor Tile	110 SF	Misc.	NF	MNO	MNO	7	Abated in 2024 by OneSource
<b>Second Floor</b>								
Hall Closet	Cementitious Panel Flooring		Misc.	NF	MNO	MNO	7	Abated in 2024 by OneSource
A-1 Kitchen	Sheet Flooring	63 SF	Misc.	NF	MNO	MNO	5, 8	Material has been covered over with newer flooring.
Bath	Sheet Flooring	20 SF	Misc.	NF	MNO	MNO	5, 8	
All Gender's Bathroom (Previously listed as Men's Bathroom)	Sheet Flooring	12 SF	Misc.	NF	MNO	MNO	5, 8	
Office Storage	Sheet Flooring	16 SF	Misc.	NF	MNO	MNO	5, 8	
Staircase 115-315 from porch	12" Floor Tile	110 SF	Misc.	NF	MNO	MNO	7	Abated in 2024 by OneSource
<b>Third Floor</b>								
Hall and Bathroom 307	Sheet Flooring	175 SF	Misc.	NF	MNO	MNO	7	Abated in 2024 by Environvantage
Apt. 4, Bathroom	Sheet Flooring	75 SF	Misc.	NF	MNO	MNO	5,8	
Apt 5, Bathroom	Sheet Flooring	100 SF	Misc.	NF	MNO	MNO	7	Confirmed non-ACBM in 2023 testing by RPF
Hall (Data) Closet	Cementitious Board Flooring	5 SF	Misc.	NF	MNO	MNO	7	Abated in 2024 by OneSource

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Alumni Hall-7 Rectory Road								
Third Floor, continued								
Staircase 115-315 from porch	12" Floor Tile	100 SF	Misc.	NF	MNO	MNO	5, 8	Abated in 2024 by OneSource
Throughout	Other suspect materials are present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation of demolition work.						6	See further discussion in report. Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACBM; 2. Damaged friable surfacing ACBM; 3. Significantly damaged friable surfacing ACBM; 4. Damaged or significantly damaged friable miscellaneous ACBM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACBM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference the report, code description sheet, and the school management plan for discussion on assessment codes								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
School House								
Basement								
Safe	9" Floor Tile	140 SF	Misc.	NF	Good	NF	5	Maroon and black checker pattern.
Basement	Pipe Insulation		TSI	Yes	MNO	MNO	5, 8	Material is located above the ceiling.
	Pipe Fitting Insulation		TSI	Yes	MNO	MNO	5, 8	
Basement Electrical Room 017	9" Floor Tile	36 SF	Misc.	NF	Damaged	NF	3	ACBM flooring is observed under the electrical switchgear. Fragmented tile edges observed extending beyond footprint of "switchgear" fixture. 2024 testing by GZA confirmed materials as ACBM.
Third Floor								
Room 312 Closet	9" Floor Tile	20 SF	Misc.	NF	Good	NF	5	Brown with white grain pattern. 2024 testing by GZA confirmed materials as ACBM.
Registrar's Office Closet	9" Floor Tile	30 SF	Misc.	NF	Good	NF	5	
Throughout	Other suspect materials are present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation of demolition work.						6	See further discussion in report. Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 404 Physical Plant/Maintenance								
Boiler Room								
Hall entrance to boiler room	Fire Door	1 Door	Misc.	MNO	MNO	MNO	5, 8	Material is assumed to be present underneath metal jacket.
Facilities Building								
Facilities Director office (former reception)	Pipe Fitting Insulation		TSI	Yes	MNO	MNO	5, 8	Material was not observed and may be above ceiling or within the wall space.
	Pipe Insulation		TSI	Yes	MNO	MNO	5, 8	
Maintenance and Secretaries offices	Pipe Insulation		TSI	Yes	MNO	MNO	5, 8	
	Pipe Fitting Insulation		TSI	Yes	MNO	MNO	5, 8	
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	See further discussion in report. Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								



### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 51 New Chapel								
First Floor								
Choir	Flooring Paper	675 SF	Misc.	NF	Good	7	5	Material is located under the wood flooring. A brown, fibrous flooring paper was observed inside floor vent under wood flooring in the choir.
Side entrance near choir	Flooring Paper	100 SF	Misc.	NF	MNO	MNO	5, 8	
Sacristy Hall	Flooring Paper	475 SF	Misc.	NF	MNO	MNO	5, 8	
Sacristy	Flooring Paper	220 SF	Misc.	NF	MNO	MNO	5, 8	
Exterior	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 402 Scudder House, 15 Rectory Road (The Guest House)								
Second Floor								
Bathroom	9" Floor Tile	75 SF	Misc.	No	Damaged	NF	5	
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4. Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 11 Friedman Center - (Previously Hargate Art Center)								
Attic								
Mechanical room	Fire proofing coating, beige	15,000 SF	Surfacing	Yes	Good	5	5	Some material has been covered over with gypsum board with some exposed surfaces.
Mechanical room	Wall tile adhesive, tan	10 LF	Misc.	NF	Damaged	NF	3	Exposed and behind white ceramic tiles used as cove base.
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 414 Food Services - Coit Hall								
First Floor								
Upper Dining Room	Flooring Paper	3,500 SF	Misc.	NF	MNO	MNO	5, 8	Materials underneath the wood flooring have been covered over
Second Floor								
Food Services storage room	Flooring Paper	240 SF	Misc.	NF	MNO	MNO	5, 8	Materials underneath the wood flooring and tile, have been covered over with vinyl plank flooring.
Women's Locker Room	Flooring Paper	160 SF	Misc.	NF	MNO	MNO	5, 8	
Men's Locker Room	Flooring Paper	200 SF	Misc.	NF	MNO	MNO	5, 8	
Women's Room	Flooring Paper	80 SF	Misc.	NF	MNO	MNO	5, 8	
Break Room	Flooring Paper	225 SF	Misc.	NF	MNO	MNO	5, 8	
Linen Storage	Flooring Paper	225 SF	Misc.	NF	MNO	MNO	5, 8	
Corridor	Flooring Paper	100 SF	Misc.	NF	MNO	MNO	5, 8	
Third Floor								
Guest Bathroom	Flooring Paper	130 SF	Misc.	NF	MNO	MNO	5, 8	Materials underneath the wood flooring and tile, have been covered over with vinyl plank flooring.
Guest Bathroom	12" Floor tile, cream with white mottle	130 SF	Misc.	NF	Good	NF	5	Observed during AHERA re-inspection, assumed ACBM.
Resident Bathroom	Flooring Paper	60 SF	Misc.	NF	MNO	MNO	5, 8	Materials underneath the wood flooring and tile, have been covered
Corridor	Flooring Paper	360 SF	Misc.	NF	MNO	MNO	5, 8	
Fourth Floor								
Room 16	Flooring Paper	120 SF	Misc.	NF	MNO	MNO	5, 8	Materials underneath the wood flooring and tile, have been covered over with vinyl plank flooring.
Room 17	Flooring Paper	160 SF	Misc.	NF	MNO	MNO	5, 8	
Room 18	Flooring Paper	160 SF	Misc.	NF	MNO	MNO	5, 8	
Room 19	Flooring Paper	160 SF	Misc.	NF	MNO	MNO	5, 8	
Linen Storage	Flooring Paper	50 SF	Misc.	NF	MNO	MNO	5, 8	
Room 20	Flooring Paper	140 SF	Misc.	NF	MNO	MNO	5, 8	
Room 21	Flooring Paper	200 SF	Misc.	NF	MNO	MNO	5, 8	
Corridor	Flooring Paper	300 SF	Misc.	NF	MNO	MNO	5, 8	

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 414 Food Services - Coit Hall								
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.					6	Possible inaccessible ACBM also.	
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACBM; 2. Damaged friable surfacing ACBM; 3. Significantly damaged friable surfacing ACBM; 4. Damaged or significantly damaged friable miscellaneous ACBM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACBM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference the report, code description sheet, and the school management plan for discussion on assessment codes								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4. Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 406 - Bookstore (previously listed as Post Office)								
Basement								
Throughout	Trowelled-on surfacing material	8,800 SF	Surfacing	NF	Good	5	5, 6	
First Floor								
Post Master Area	Trowelled-on surfacing material	1,477 SF	Surfacing	NF	Good	5	6	
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.							Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4. Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Red Barn - 15 Dunbarton Road								
First Floor								
Shop	Cementitious Panel Ceiling	600 SF	Misc.	NF	MNO	MNO	5, 8	Materials observed to have been enclosed with spray foam insulation.
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4. Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 411 - Service Building (White Farm Garage)								
Basement								
Boiler Room	Cementitious Panels	24 LF	Misc.	NF	Damaged	NF	3	Rough edges and broken cementitious panels observed above wall at the deck.
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								



### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Nash Hall - 70 Rectory Road								
Basement								
Custodial Closet	9" Floor tile and mastic	28 SF	Misc.	NF	MNO	MNO	7	Material abated in 2024 by One Source
First Floor								
Student Room 10	9" Floor tile and mastic	216 SF	Misc.	NF	MNO	MNO	5, 8	New flooring material observed
Student Room 11	9" Floor tile and mastic	230 SF	Misc.	NF	MNO	MNO	5, 8	
Student Room 12	9" Floor tile and mastic	230 SF	Misc.	NF	MNO	MNO	5, 8	
Student Room 13	9" Floor tile and mastic	230 SF	Misc.	NF	MNO	MNO	5, 8	
Student Room 14	9" Floor tile and mastic	230 SF	Misc.	NF	MNO	MNO	5, 8	
Student Room 15	9" Floor tile and mastic	230 SF	Misc.	NF	MNO	MNO	5, 8	
Student Room 16	9" Floor tile and mastic	216 SF	Misc.	NF	MNO	MNO	5, 8	
Corridor	9" Floor tile and mastic	128 SF	Misc.	NF	MNO	MNO	5, 8	Material abated in 2024 by One Source
Custodial Closet	9" Floor tile and mastic	28 SF	Misc.	NF	MNO	MNO	5, 8	
Second Floor								
Student Room 20	9" Floor tile and mastic	170 SF	Misc.	NF	MNO	MNO	5, 8	New flooring material observed
Student Room 21	9" Floor tile and mastic	121 SF	Misc.	NF	MNO	MNO	5, 8	Material covered over with carpet.
Student Room 22	9" Floor tile and mastic	121 SF	Misc.	NF	MNO	MNO	5, 8	Material covered over with carpet.
Student Room 23	9" Floor tile and mastic	121 SF	Misc.	NF	MNO	MNO	7	New flooring material observed
Student Room 24 (former)	9" Floor tile and mastic	121 SF	Misc.	NF	MNO	MNO	5, 8	Material covered over with carpet.
Student Room 25 (former)	9" Floor tile and mastic	121 SF	Misc.	NF	Good	NF	5, 8	New flooring material observed
Student Room 26 (renamed 201)	9" Floor tile and mastic	170 SF	Misc.	NF	MNO	MNO	5, 8	
Student Room 27 (former)	9" Floor tile and mastic	220 SF	Misc.	NF	MNO	MNO	5, 8	New flooring material observed

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Nash Hall - 70 Rectory Road								
Corridor	9" Floor tile and mastic	500 SF	Misc.	NF	MNO	MNO	5, 8	
Room 211	Levelastic, light gray	121 SF	Surf.	NF	Good	7	5	Material confirmed as ACBM in testing performed by GZA in 2024.
	9" Floor tile and mastic	121 SF	Misc.	NF	MNO	MNO	5, 8	Spot abatement by OneSource in 2024. Material covered over with carpet.
Room 215	Levelastic, light gray	121 SF	Surf.	NF	Good	7	5	Material confirmed as ACBM in testing performed by GZA in 2024.
	9" Floor tile and mastic	121 SF	Misc.	NF	MNO	MNO	5, 8	Spot abatement by OneSource in 2024. Material covered over with carpet.
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	See further discussion in report. Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACBM; 2. Damaged friable surfacing ACBM; 3. Significantly damaged friable surfacing ACBM; 4. Damaged or significantly damaged friable miscellaneous ACBM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACBM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference the report, code description sheet, and the school management plan for discussion on assessment codes								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4. Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 330 - 35 Armour Place (The Forty-Four House)								
Basement								
Basement Bathroom	Floor Tile	40 SF	Misc.	NF	MNO	MNO	5, 8	Materials have been covered over
Basement, Northwest Bedroom	Floor Tile	260 SF	Misc.	NF	MNO	MNO	5, 8	Materials have been covered over with vinyl plank flooring.
Southwest Bedroom	Floor Tile	260 SF	Misc.	NF	MNO	MNO	5, 8	
Hall	Floor Tile	200 SF	Misc.	NF	MNO	MNO	5, 8	
Hall Closet	12" Floor Tile	10 SF	Misc.	NF	Good	NF	5	Black floor tile with bronze mottled pattern observed.
First Floor								
First Floor Bathroom	Floor Tile	50 SF	Misc.	NF	MNO	MNO	5, 8	Materials have been covered over with 8" ceramic tile.
Kitchen	Floor Tile	180 SF	Misc.	NF	MNO	MNO	5, 8	Materials have been covered over with 12" ceramic tile.
Enclosed Porch	Cementitious Board Flooring	240 SF	Misc.	NF	MNO	MNO	5, 8	Materials have been covered over with carpet.
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	See further discussion in report. Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 331- 41 Armour Place								
Basement								
Hall Closet	12" Floor Tile	10 SF	Misc.	No	Good	NF	5	Black with bronze tile, mottled pattern observed
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
<b>Category:</b> MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
<b>Assessment Codes</b> based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
<b>Response Codes:</b> 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 329- 47 Armour Place (The Eighteen House)								
Basement								
Basement, Northwest Bedroom	Floor Tile	280 SF	Misc.	NF	MNO	MNO	5, 8	Site Representative indicated this material has been covered over with newer flooring.
Basement, Bathroom	Floor Tile	70 SF	Misc.	NF	MNO	MNO	5, 8	
SE Bedroom	Floor Tile	250 SF	Misc.	NF	MNO	MNO	5, 8	
SW Bedroom	Floor Tile	250 SF	Misc.	NF	MNO	MNO	5, 8	
Hall	Floor Tile	200 SF	Misc.	NF	MNO	MNO	5, 8	
Closet	12" Floor Tile	10 SF	Misc.	NF	Good	NF	5	Black with bronze tile, mottled pattern observed.
First Floor								
Kitchen	Floor Tile	150 SF	Misc.	NF	MNO	MNO	5, 8	Site Representative indicated this material has been covered over with newer flooring.
First Floor Bathroom	Floor Tile	80 SF	Misc.	NF	MNO	MNO	5, 8	
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	See further discussion in report. Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 254- 212 Dunbarton Road								
First Floor								
Bathroom	Sheet Flooring	94 SF	Misc.	NF	Good	NF	5	Material observed under newer flooring.
Kitchen	Sheet Flooring	300 SF	Misc.	NF	MNO	MNO	5, 8	Site representative indicated this material has been covered over with newer flooring.
Throughout	Flooring Paper	1,000 SF	Misc.	Yes	Good	7	6	Black flooring paper observed under wood flooring.
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 332 - 1 Silk Farm Road								
Attic								
Attic crawlspace	Vermiculite Insulation, White/Grey	1,440 SF	TSI	Yes	Damaged	1	5	Tested in 2011 by RPF Associates (#114540), lab analysis identified trace amounts of asbestos content present. Material was observed under blown-in insulation.
Basement								
Basement	Vermiculite Insulation debris, White/Grey	20 SF	TSI	Yes	Significantly Damaged	1	1	Debris observed on walls and floors under pipe riser penetrations
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4. Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 261 (Demolished in May 2023)								
First Floor								
Bathroom	Sheet Flooring		Misc.	NF	MNO	MNO	7	
Kitchen	Sheet Flooring		Misc.	NF	MNO	MNO	7	
Laundry	Sheet Flooring		Misc.	NF	MNO	MNO	7	
Hall	Sheet Flooring		Misc.	NF	MNO	MNO	7	
Second Floor								
Bathroom	Sheet Flooring		Misc.	NF	MNO	MNO	7	
Third Floor								
Third Floor Bathroom	Sheet Flooring		Misc.	NF	MNO	MNO	7	
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								



### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 249 - 89 Dunbarton Road								
First Floor								
Kitchen	Sheet Flooring	130 SF	Misc.	NF	MNO	MNO	5, 8	Site representative indicated this material has been covered over with newer flooring.
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.							Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
<b>Category:</b> MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
<b>Assessment Codes</b> based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
<b>Response Codes:</b> 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4. Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 264 - 34 Rectory Road								
Basement								
Basement and mechanical room	Pipe Insulation	4" diameter, three locations observed	TSI	Yes	Significantly Damaged	1	2	Observed on risers in wall cavities, layered paper insulation with exposed ends.
Basement and mechanical room	Pipe Insulation	3" diameter, four locations observed	TSI	Yes	Significantly Damaged	1	2	Corrugated style pipe insulation observed on pipe risers in wall cavities, with exposed ends. Confirmed ACBM by testing performed by GZA in 2024.
Attic								
Attic crawlspace	Duct Insulation	18" diameter by 24 LF.	TSI	No	Good	5	5	Material is labeled as ACBM. Material sampled and confirmed ACBM during 2024 re-inspection.
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 304 - 31 Hockey Lane								
Basement								
Basement	Pipe Insulation		TSI	Yes	MNO	MNO	5, 8	Material has been enclosed and is inaccessible. The material continues into the steam tunnel to Coit Hall.
First Floor								
Kitchen, laundry, hall and 1/2 bathroom	Sheet Flooring, white-tan	430 SF	Misc.	NF	Good	5	5	Older flooring observed at heater pipe riser.
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACM with potential for damage; 6. ACM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference the report, code description sheet, and the management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Sites 245, 246 - 117 Dunbarton Road (Old Miller House)								
Site 245								
Kitchen	Sheet Flooring	200 SF	Misc.	NF	Good	NF	5	Material observed under newer flooring.
First Floor Bathroom	Sheet Flooring	50 SF	Misc.	NF	Good	NF	5	
Second Floor Bathroom	Sheet Flooring	50 SF	Misc.	NF	Good	NF	5	
Washroom	Sheet Flooring	50 SF	Misc.	NF	Good	NF	5	
Site 246								
Laundry	Sheet Flooring	50 SF	Misc.	NF	Good	NF	5	Material observed under newer flooring.
Kitchen	Sheet Flooring	160 SF	Misc.	NF	Good	NF	5	
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	See further discussion in report. Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4. Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 248 - 134 Dunbarton Road								
First Floor								
Kitchen	Sheet Flooring	260 SF	Misc.	NF	MNO	MNO	5, 8	Site representative indicated this material has been covered over with newer flooring.
Bathroom	Sheet Flooring	24 SF	Misc.	NF	MNO	MNO	5, 8	
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								
Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
Assessment Codes based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
Response Codes: 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4.Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
<b>Site 113 - Kittredge</b>								
<b>Apartment 280</b>								
<b>First Floor</b>								
Bathroom	Floor tile	40 SF	Misc.	NF	MNO	NF	5, 8	Site representative indicated this material has been covered over with new flooring.
Kitchen	Floor tile	100 SF	Misc.	NF	MNO	NF	5, 8	
	Cementitious panel	5 SF	Misc.	NF	Good	NF	5	Inside pocket door track
<b>Second Floor</b>								
Bathroom	Floor Tile	50 SF	Misc.	NF	MNO	NF	5, 8	Site representative indicated this material has been covered over with new flooring.
Bedroom	Window glaze, hard	90 LF	Misc.	NF	Good	NF	5	
Living room	Window glaze, hard	44 LF	Misc.	NF	Good	NF	5	
Garden room	Window glaze, pliable	20 LF	Misc.	NF	Good	NF	5	
<b>Third Floor</b>								
Corridor	Cementitious panel	5 SF	Misc.	NF	Good	NF	5	Dumbwaiter, ceiling
<b>Apartment 281</b>								
<b>First Floor</b>								
Bathroom	Floor tile	40 SF	Misc.	NF	MNO	NF	5, 8	Sheet flooring observed
Kitchen	Floor tile	48 SF	Misc.	NF	MNO	NF	5, 8	Site representative indicated this material has been covered over with new flooring. Quarry tile observed.
	Cementitious panel	5 SF	Misc.	NF	MNO	NF	5, 8	Material previously reported to be associated with the pocket door.
Bedroom	Window glaze, hard	90 LF	Misc.	NF	Good	NF	5	
Kitchen/dining/living	Window glaze, hard	44 LF	Misc.	NF	Damaged	NF	3	

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
<b>Site 113 - Kittredge</b>								
<b>Apartment 283</b>								
<b>Second floor</b>								
Kitchen	Floor tile	300 SF	Misc.	NF	MNO	NF	5, 8	Site representative indicated this material has been covered over with new flooring.
	Cementitious panel	5 SF	Misc.	NF	Good	NF	5, 8	Inside pocket door track
Kitchen/dining	Window glaze, hard	44 LF	Misc.	NF	Good	NF	5	
Living room	Window glaze, hard	90 LF	Misc.	NF	Good	NF	5	
<b>Third Floor</b>								
Bathroom	Floor tile	40 SF	Misc.	NF	MNO	NF	5, 8	Site representative indicated this material has been covered over with new flooring.
<b>Apartment 284</b>								
<b>Second Floor</b>								
Kitchen	Floor tile	300 SF	Misc.	NF	MNO	NF	5, 8	Site representative indicated this material has been covered over with new flooring.
	Cementitious panel	5 SF	Misc.	NF	Good	NF	5, 8	Inside pocket door track
<b>Third Floor</b>								
Bathroom	Floor tile	24 SF	Misc.	NF	MNO	NF	5, 8	Site representative indicated this material has been covered over with new flooring.

### SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
Site 113 - Kittredge								
Apartment 285								
Second Floor								
Bathroom	Floor tile	24 SF	Misc.	NF	MNO	NF	5, 8	Site representative indicated this material has been covered over with new flooring.
Kitchen	Cementitious panel	5 SF	Misc.	NF	MNO	NF	5, 8	Material was reported to be associated with a pocket door. Door was not observed within the apartment.
Kitchen/dining	Window glaze, hard	44 LF	Misc.	NF	Damaged	NF	3	
Living room	Window glaze, hard	90 LF	Misc.	NF	Good	NF	5	
Third Floor								
Bathroom	Floor tile	24 SF	Misc.	NF	MNO	NF	5, 8	Site representative indicated this material has been covered over with new flooring.
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.						6	Possible inaccessible ACBM also.
Apartment 286								
First Floor								
Bathroom	Floor tile	40 SF	Misc.	NF	MNO	NF	5, 8	Sheet flooring observed
Kitchen	Floor tile	48 SF	Misc.	NF	MNO	NF	5, 8	Site representative indicated this material has been covered over with new flooring. Quarry tile observed.
Kitchen	Cementitious panel	5 SF	Misc.	NF	MNO	NF	5, 8	Material previously reported to be associated with the pocket door.



## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
<b>Site 113 - Kittredge</b>								
<b>Apartment 286</b>								
<b>Second Floor</b>								
Bathroom	Floor Tile	50 SF	Misc.	NF	MNO	NF	5, 8	Sheet flooring observed
Bedroom	Window glaze, hard	90 LF	Misc.	NF	Good	NF	5	
Living room	Window glaze, hard	44 LF	Misc.	NF	Good	NF	5	
Garden room	Window glaze, pliable	20 LF	Misc.	NF	Good	NF	5	
<b>Third Floor</b>								
Bathroom	Floor tile	40 SF	Misc.	NF	MNO	NF	5, 8	Sheet flooring observed
LF = Linear feet, SF- Square Feet								
<b>Category:</b> MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.								
<b>Assessment Codes</b> based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.								
<b>Response Codes:</b> 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4. Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.								

## SPS: 3-Year AHERA Reinspection 2024

Location	ACBM	Approximate Quantity	Category	Friable	Condition	Assessment	Response	Notes
<b>Site 234 - 7 Fisk Road</b>								
<b>First Floor</b>								
Wall chases	Pipe Insulation		TSI	Yes	MNO	MNO	5, 8	
<b>Second Floor</b>								
Bathroom, west	Floor Tile	100 SF	Misc.	NF	MNO	NF	5, 8	Site representative indicated this material has been covered over with ceramic flooring.
Throughout	Other suspect materials are present and further review is required. Prior to any renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state						6	Possible inaccessible ACBM also.
LF = Linear feet, SF- Square Feet								

**Category:** MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.

**Assessment Codes** based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantly damaged friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACM with potential for damage; 6. ACM with potential for significant damage; 7. Any remaining ACM. "NF" means nonfriable, and assessments are not required. MNO means material not observed. Please reference AHERA and the school management plan for discussion on assessment codes.

**Response Codes:** 1. Evacuate or isolate the area if needed, conduct removal and cleaning ; 2. Evacuate or isolate the area if needed and remove, enclose, encapsulate, or repair to correct damage and clean work area. Take steps to reduce potential for disturbance; 3. Remove, enclose, encapsulate, or repair to correct damage, clean work area; 4. Evacuate or isolate the area if needed, take steps to reduce potential for disturbance; 5. Manage ACBM in accordance with Management Plan; 6. Material suspect and requires further testing; 7. ACBM has been removed and may be removed from listings; 8. ACBM was not observed and further review is required. See further discussion and requirements in report.