

March 2020

| Location  | ACBM                         | Approximate Quantity | Category | Friable | Condition 3 year October 2018 | Condition 6 month - MARCH 2020 | Notes   |
|---|------------------------------|----------------------|----------|---------|-------------------------------|--------------------------------|---|
| <b>Site No. 55 Memorial</b>                               |                              |                      |          |         |                               |                                |   |
| <b>Basement</b>   |                              |                      |          |         |                               |                                |   |
| Radio Station Mech  | Pipe Insulation              | ----                 | TSI      | Yes     | MNO                           | 1,6                            | Material is located above the finished ceiling.   |
| Radio Station Mech  | Pipe Fitting Insulation      | ----                 | TSI      | Yes     | MNO                           | 1,6                            |   |
| Radio Station Mech  | Duct Skim Coat               | ----                 | TSI      | Yes     | MNO                           | 1,6                            |   |
| Band Room   | 9" Floor Tile                | 500 sq. ft.          | Misc.    | MNO     | MNO                           | 1,6                            | Materials have been covered over with carpet.   |
| Women's Dressing Rm                                       | 9" Floor Tile                | 75 Sq. Ft.           | Misc     | No      | Fair                          | 1, 2                           | Materials need to be waxed. <i>WO complete</i>  |
| Theater Storage (013)                                     | Pipe Insulation              | 4 linear feet        | TSI      | Yes     | Good                          | 1                              | Materials is located above the ductwork/closet area.  |
| Mechanical 012  | Duct Expansion Cloth         | 6 Linear ft.         | Misc     | No      | Fair                          | 1                              | Materials were observed to have water staining present, < 1 lf.   |
| Hall and Foyer outside restrooms end entry to ladies room | 9" Floor Tile                | 580 sq. ft           | Misc     | No      | Fair                          | 1                              | Normal wear throughout with dents, scratches present throughout. Water damage by bubbler.                                     |
| Storage (002)   | 9" Floor Tile                | 80 sq. ft            | Misc     | No      | Good                          | 1                              | Mostly stored items present. School bookstore owns this space and does not have access.                                       |
| <b>First Floor</b>  |                              |                      |          |         |                               |                                |   |
| Stage   | Fire Curtain                 | 1 Curtain            | Misc.    | Yes     | Good                          | 1                              | Suspect, test prior to removal.   |
| Stairwell hall  | 9" Floor tile                | 300 sq. ft           | Misc.    | No      | MNO                           | 1,6                            | Materials have been covered over with carpet.   |
| Auditorium  | 9" Floor tile                | 4,100 sq. ft         | Misc.    | No      | Fair                          | 1, 2                           | Materials observed to have some chipped, dented floor tiles present. Two floor tiles in front row broken with mastic exposed. |
| <b>Second Floor</b>                                       |                              |                      |          |         |                               |                                |   |
| North Stairwell and lobby                                 | 9" Floor Tile                | 540 Sq. Ft.          | Misc     | No      | Good                          | 1                              |   |
| Auditorium Ceiling  | Trowel On Surfacing Material | 4,800 sq. ft         | Surf     | Yes     | Good                          | 1                              |   |

March 2020

|                           |                              |                |       |     |      |      |   |
|---------------------------|------------------------------|----------------|-------|-----|------|------|---|
| Auditorium Balcony        | 9" Floor Tile                | 2,100 sq. ft   | Misc  | No  | Fair | 1, 2 | Material was observed to have some chipped and missing floor tiles present. |
| Auditorium & Balcony Wall | Trowel On Surfacing Material | 400 Sq. Ft.    | Surf  | Yes | Good | 1    |   |
| Projector Room            | Light wire                   | 2 Linear Ft.   | Misc  | No  | Good | 1    | Materials are assumed to be ACM.  |
| Attic                     | Duct Expansion Cloth         | 40 linear feet | Misc. | No  | Good | 1    | Materials are assumed to be ACM.  |

**Site 013 Music & Dance**

**Music**

|                           |                            |            |      |    |      |   |  |
|---------------------------|----------------------------|------------|------|----|------|---|--|
| Exterior: West Side Music | Corrugated transite siding | 800 sq. ft | Misc | No | Good | 1 |  |
|---------------------------|----------------------------|------------|------|----|------|---|--|

**Dance**

|                      |                            |              |      |    |      |   |  |
|----------------------|----------------------------|--------------|------|----|------|---|--|
| Exterior: North Side | Corrugated transite siding | 1,500 sq. ft | Misc | No | Good | 1 |  |
|----------------------|----------------------------|--------------|------|----|------|---|--|

**Alumni Hall**

|   |                |             |      |    |      |      |   |
|---|----------------|-------------|------|----|------|------|---|
| <b>First Floor</b>  |                |             |      |    |      |      |   |
| 107/108 Office  | Floor Tile     | 486 Sq. Ft. | Misc | No | MNO  | 1, 6 | Material has been covered over with carpeting.      |
| 101/120/119 Business Office                               | Floor Tile     | 486 Sq. Ft. | Misc | No | MNO  | 1, 6 |   |
| 110/111 Human Resources                                   | Floor Tile     | 405 Sq. Ft. | Misc | No | MNO  | 1, 6 |   |
| <b>Second Floor</b>                                       |                |             |      |    |      |      |   |
| 2nd Floor, Hall Closet                                    | Transite floor | 10 sq. ft   | Misc | No | Good | 1    | Material has been covered over with newer flooring. |
| 2nd Floor, A-1 Kitchen                                    | Linoleum       | 63 Sq. Ft.  | Misc | No | MNO  | 1, 6 |   |
| 2nd Floor, A-1 Bath                                       | Linoleum       | 20 Sq. Ft.  | Misc | No | MNO  | 1, 6 |   |
| All gender bathroom (previously listed as Men's Bathroom) | Linoleum       | 12 Sq. Ft.  | Misc | No | MNO  | 1, 6 |   |
| Office Storage  | Linoleum       | 16 Sq. Ft.  | Misc | No | MNO  | 1, 6 |   |
| <b>Third Floor</b>  |                |             |      |    |      |      |   |
| Hall, Bath  | Linoleum       | 75 sq. ft   | Misc | No | MNO  | 1, 6 | Material has been covered over with newer flooring. |
| Apt. 4, Bath  | Linoleum       | 75 sq. ft   | Misc | No | MNO  | 1, 6 |   |
| Apt. 5, Bath  | Linoleum       | 100 sq. ft  | Misc | No | MNO  | 1, 6 |   |
| Hall Closet   | Transite floor | 5 sq. ft    | Misc | No | Good | 1    |   |

**Fine Arts Building (formerly Moore Building)**

|   |                          |                        |                 |                |                |   |   |
|---|--------------------------|------------------------|-----------------|----------------|----------------|---|---|
| <del>Woman's bath</del>                         | <del>9" Floor Tile</del> | <del>150 sq. ft</del>  | <del>Misc</del> | <del>MNO</del> | <del>MNO</del> | 5 | Materials were removed by EnviroVantage during the 2016 renovations |
| <del>Room 11 previously listed as room 45</del> | <del>9" Floor Tile</del> | <del>441 Sq. Ft.</del> | <del>Misc</del> | <del>No</del>  | <del>MNO</del> | 5 |   |

March 2020

|   |                         |             |      |     |     |   |
|---|-------------------------|-------------|------|-----|-----|---|
| <del>Room 14 previously listed as room 47</del> | 9" Floor Tile           | 441 Sq. Ft. | Misc | No  | MNO | 5 |
| <del>Room 15 previously listed as room 48</del> | 9" Floor Tile           | 441 Sq. Ft. | Misc | No  | MNO | 5 |
| <del>Room 13 previously listed as room 46</del> | 9" Floor Tile           | 441 Sq. Ft. | Misc | No  | MNO | 5 |
| <del>Room 19 previously listed as room 49</del> | 9" Floor Tile           | 441 Sq. Ft. | Misc | No  | MNO | 5 |
| <del>Room 24 previously listed as room 42</del> | 9" Floor Tile           | 432 Sq. Ft. | Misc | No  | MNO | 5 |
| <del>Room 21 previously listed as room 43</del> | 9" Floor Tile           | 441 Sq. Ft. | Misc | No  | MNO | 5 |
| <del>Room 22 previously listed as room 40</del> | 9" Floor Tile           | 432 Sq. Ft. | Misc | No  | MNO | 5 |
| <del>Room 23 previously listed as room 41</del> | 9" Floor Tile           | 441 Sq. Ft. | Misc | No  | MNO | 5 |
| Entrance Rooms 24                               | 9" Floor Tile           | 81 Sq. Ft.  | Misc | No  | MNO | 5 |
| Lower level-                                    | Pipe fitting insulation | 25 observed | TSI  | MNO | MNO | 5 |

**School House**

|                             |                 |            |      |     |      |      |   |
|-----------------------------|-----------------|------------|------|-----|------|------|---|
| <b>Basement</b>             |                 |            |      |     |      |      |   |
| Safe                        | 9" Floor Tile   | 140 sq. ft | Misc | No  | Good | 1    |   |
| Basement Ceiling            | Pipe Insulation | -----      | TSI  | MNO | MNO  | 1, 6 | Material is located above the ceiling.  |
| Basement Ceiling            | Pipe Fittings   | -----      | TSI  | MNO | MNO  | 1, 6 |   |
| Basement Electrical Room-17 | 9" Floor Tile   | -----      | Misc | MNO | MNO  | 1, 6 | Majority of material removed by ABS in 2008. Remaining material is present under the electrical switchgear (20 sq. ft. approx) and is inaccessible. |
|                             |                 | -----      | Misc | MNO | MNO  | 1, 6 |   |
| <b>Third Floor</b>          |                 |            |      |     |      |      |   |
| Room 312 Closet             | 9" Floor Tile   | 20 Sq. Ft. | Misc | No  | Good | 1    |   |
| Registrar's Office Closet   | 9" Floor Tile   | 30 Sq. ft  | Misc | No  | Good | 1    |   |

**Physical Plant/Maintenance: Site No. 404**

**Boiler Room**

|                              |           |        |       |     |     |      |  |
|------------------------------|-----------|--------|-------|-----|-----|------|--|
| Hall entrance to boiler room | Fire Door | 1 Door | Misc. | MNO | MNO | 1, 6 | Material is assumed to be present underneath metal jacket. |
|------------------------------|-----------|--------|-------|-----|-----|------|--|

**Facilities Building**

March 2020

|  |                         |       |     |     |     |      |  |
|--|-------------------------|-------|-----|-----|-----|------|--|
| Facilities Director office<br>(former reception/key<br>office) | Pipe Fitting Insulation | ----- | TSI | MNO | MNO | 1, 6 | Material was not observed and may be<br>above the sheetrock ceiling or within<br>the wall space. |
|  | Pipe Insulation         | ----- | TSI | MNO | MNO | 1, 6 |  |
| Maintenance and<br>Secretaries offices                         | Pipe Insulation         | ----- | TSI | MNO | MNO | 1, 6 | Material was not observed and may be<br>above the sheetrock ceiling or within<br>the wall space. |
| Maintenance and<br>Secretaries offices                         | Pipe Fitting Insulation | ----- | TSI | MNO | MNO | 1, 6 |  |

**New Chapel: Site 51**

|                          |                |            |      |     |     |      |   |
|--------------------------|----------------|------------|------|-----|-----|------|---|
| Choir                    | Flooring Paper | 675 sq. ft | Misc | Yes | MNO | 1, 6 | Material is located under the wood<br>flooring. |
| Side Entrance near choir | Flooring Paper | 100 sq. ft | Misc | MNO | MNO | 1, 6 |   |
| Sacristy Hall            | Flooring Paper | 475 sq. ft | Misc | MNO | MNO | 1, 6 |   |
| Sacristy                 | Flooring Paper | 220 sq. ft | Misc | MNO | MNO | 1, 6 |   |

**Scudder House: Site No. 402**

**Second Floor**

|          |               |           |       |    |      |   |  |
|----------|---------------|-----------|-------|----|------|---|--|
| Bathroom | 9" Floor Tile | 75 sq. ft | Misc. | No | Good | 1 | Prior to removal testing is<br>recommended. Limited access to the<br>materials due to stored materials<br>present. |
|----------|---------------|-----------|-------|----|------|---|--|

**Friedman Center: Site No. 11**

|   |                                       |                          |                           |                |                |   |  |
|---|---------------------------------------|--------------------------|---------------------------|----------------|----------------|---|--|
| <del>2nd floor: Classroom 045,<br/>office 46, Corridor 47, stair<br/>landing to projector room<br/>and storage closet</del> | <del>covebase mastie</del>            | <del>385 lf.</del>       | <del>Misc.</del>          | <del>MNO</del> | <del>MNO</del> | 5 | Materials were removed during the<br>2016-2017 renovations |
| <del>Exhibition 034, storage<br/>031 and storage 036</del>  | <del>Flooring mastie</del>            | <del>2,500 sq. ft.</del> | <del>Misc.</del>          | <del>MNO</del> | <del>MNO</del> | 5 |  |
| <del>2nd floor: Classroom 045,<br/>office 46, Corridor 47, stair<br/>landing to projector room<br/>and storage closet</del> | <del>12" Floor tile with mastie</del> | <del>725 sq. ft.</del>   | <del>Misc.</del>          | <del>MNO</del> | <del>MNO</del> | 5 |  |
| <del>Classroom 045, Kitchen<br/>040, Apartment 306 and<br/>Apartment 307</del>  | <del>Sink basin undercoat</del>       | <del>8 sq. ft.</del>     | <del>Misc.</del>          | <del>MNO</del> | <del>MNO</del> | 5 |  |
| <del>Art Library</del>  | <del>Textured Ceiling Material</del>  | <del>450 sq. ft.</del>   | <del>Surfaci<br/>ng</del> | <del>MNO</del> | <del>MNO</del> | 5 |  |
| <del>Ceramic Tile grout</del>   | <del>Kitchen 040</del>                | <del>30 sq. ft.</del>    | <del>Misc.</del>          | <del>MNO</del> | <del>MNO</del> | 5 |  |
| <del>Linoleum</del>   | <del>Apartment 306</del>              | <del>10 sq. ft.</del>    | <del>Misc.</del>          | <del>MNO</del> | <del>MNO</del> | 5 |  |
| <del>Transite Panels</del>  | <del>Apartment 306 and 307</del>      | <del>40 sq. ft.</del>    | <del>Misc.</del>          | <del>MNO</del> | <del>MNO</del> | 5 |  |

March 2020

|                       |                         |                |           |     |     |                             |   |
|-----------------------|-------------------------|----------------|-----------|-----|-----|-----------------------------|---|
| Fire proofing coating | Throughout Attic spaces | 15,000 sq. ft. | Surfacing | MNO | MNO | 1, 6.<br>COVERING<br>INTACT | Some materials were removed during the 2016-2017 renovation, however remaining materials have been encapsulated over with gypsum board. |
|-----------------------|-------------------------|----------------|-----------|-----|-----|-----------------------------|---|

|                         |                             |                       |              |                |                |              |  |
|-------------------------|-----------------------------|-----------------------|--------------|----------------|----------------|--------------|--|
| <del>Window Caulk</del> | <del>Exterior windows</del> | <del>17 windows</del> | <del>—</del> | <del>MNO</del> | <del>MNO</del> | <del>5</del> |  |
|-------------------------|-----------------------------|-----------------------|--------------|----------------|----------------|--------------|--|

**Food Services Site 414**

**First Floor**

|                   |                |              |       |    |     |      |  |
|-------------------|----------------|--------------|-------|----|-----|------|--|
| Upper Dining room | Flooring paper | 3,500 sq. ft | Misc. | No | MNO | 1, 6 | Materials is underneath the wood flooring. |
|-------------------|----------------|--------------|-------|----|-----|------|--|

**Second Floor**

|                            |                |            |       |    |     |      |   |
|----------------------------|----------------|------------|-------|----|-----|------|---|
| Food services storage room | Flooring paper | 240 sq. ft | Misc. | No | MNO | 1, 6 | Materials is underneath the wood flooring/floor tile. |
|----------------------------|----------------|------------|-------|----|-----|------|---|

|                     |                |            |       |    |     |      |  |
|---------------------|----------------|------------|-------|----|-----|------|--|
| Women's locker room | Flooring paper | 160 sq. ft | Misc. | No | MNO | 1, 6 | Materials is underneath the wood flooring/floor tiles. |
|---------------------|----------------|------------|-------|----|-----|------|--|

|                   |                |            |       |    |     |      |
|-------------------|----------------|------------|-------|----|-----|------|
| Men's locker room | Flooring paper | 200 sq. ft | Misc. | No | MNO | 1, 6 |
|-------------------|----------------|------------|-------|----|-----|------|

|              |                |           |       |    |     |      |
|--------------|----------------|-----------|-------|----|-----|------|
| Women's room | Flooring paper | 80 sq. ft | Misc. | No | MNO | 1, 6 |
|--------------|----------------|-----------|-------|----|-----|------|

|            |                |            |       |    |     |      |
|------------|----------------|------------|-------|----|-----|------|
| Break room | Flooring paper | 225 sq. ft | Misc. | No | MNO | 1, 6 |
|------------|----------------|------------|-------|----|-----|------|

|               |                |            |       |    |     |      |  |
|---------------|----------------|------------|-------|----|-----|------|--|
| Linen Storage | Flooring paper | 225 sq. ft | Misc. | No | MNO | 1, 6 | Materials is underneath the wood flooring. |
|---------------|----------------|------------|-------|----|-----|------|--|

|          |                |            |       |    |     |      |  |
|----------|----------------|------------|-------|----|-----|------|--|
| Corridor | Flooring paper | 100 sq. ft | Misc. | No | MNO | 1, 6 | Materials is underneath the wood flooring. |
|----------|----------------|------------|-------|----|-----|------|--|

**Third Floor**

|                |                |            |       |    |     |      |  |
|----------------|----------------|------------|-------|----|-----|------|--|
| Guest bathroom | Flooring paper | 130 sq. ft | Misc. | No | MNO | 1, 6 | Materials is underneath the wood flooring. |
|----------------|----------------|------------|-------|----|-----|------|--|

|                   |                |           |       |    |     |      |
|-------------------|----------------|-----------|-------|----|-----|------|
| Resident bathroom | Flooring paper | 60 sq. ft | Misc. | No | MNO | 1, 6 |
|-------------------|----------------|-----------|-------|----|-----|------|

|          |                |            |       |    |     |      |
|----------|----------------|------------|-------|----|-----|------|
| Corridor | Flooring paper | 360 sq. ft | Misc. | No | MNO | 1, 6 |
|----------|----------------|------------|-------|----|-----|------|

**Fourth Floor**

|         |                |            |       |    |     |      |  |
|---------|----------------|------------|-------|----|-----|------|--|
| Room 16 | Flooring paper | 120 sq. ft | Misc. | No | MNO | 1, 6 | Materials is underneath the wood flooring. |
|---------|----------------|------------|-------|----|-----|------|--|

|         |                |            |       |    |     |      |
|---------|----------------|------------|-------|----|-----|------|
| Room 17 | Flooring paper | 160 sq. ft | Misc. | No | MNO | 1, 6 |
|---------|----------------|------------|-------|----|-----|------|

|         |                |            |       |    |     |      |
|---------|----------------|------------|-------|----|-----|------|
| Room 18 | Flooring paper | 160 sq. ft | Misc. | No | MNO | 1, 6 |
|---------|----------------|------------|-------|----|-----|------|

|         |                |            |       |    |     |      |
|---------|----------------|------------|-------|----|-----|------|
| Room 19 | Flooring paper | 160 sq. ft | Misc. | No | MNO | 1, 6 |
|---------|----------------|------------|-------|----|-----|------|

|               |                |           |       |    |     |      |   |
|---------------|----------------|-----------|-------|----|-----|------|---|
| Linen Storage | Flooring paper | 50 sq. ft | Misc. | No | MNO | 1, 6 | Material is underneath the wood flooring. |
|---------------|----------------|-----------|-------|----|-----|------|---|

|         |                |            |       |    |     |      |
|---------|----------------|------------|-------|----|-----|------|
| Room 20 | Flooring paper | 140 sq. ft | Misc. | No | MNO | 1, 6 |
|---------|----------------|------------|-------|----|-----|------|

|         |                |            |       |    |     |      |
|---------|----------------|------------|-------|----|-----|------|
| Room 21 | Flooring paper | 200 sq. ft | Misc. | No | MNO | 1, 6 |
|---------|----------------|------------|-------|----|-----|------|

|          |                |            |       |    |     |      |
|----------|----------------|------------|-------|----|-----|------|
| Corridor | Flooring paper | 300 sq. ft | Misc. | No | MNO | 1, 6 |
|----------|----------------|------------|-------|----|-----|------|

**Post Office: Site No. 406**

March 2020

|   |                                     |              |       |     |              |      |   |
|---|-------------------------------------|--------------|-------|-----|--------------|------|---|
| Post Master Area                                      | 9" Floor Tile and associated mastic | 690 sq. ft   | Misc. | No  | Good         | 2    | 1 Chipped floor tile - Work Order completed 3/20  |
| Post Master Area                                      | Trowelled-On Surfacing Material     | 1,477 sq. ft | Misc. | Yes | Good         | 1    |   |
| <b>Red Barn</b>                                       |                                     |              |       |     |              |      |   |
| Shop  | Transite Ceiling Panel              | 600 sq. ft   | Misc. | No  | Fair         | 2    | Approximatley 1/2 foot of damage in center of ceiling. <i>To be encapsulated</i>  |
| <b>Service Building (White Farm Garage), Site 411</b> |                                     |              |       |     |              |      |   |
| <b>Basement Level</b>                                 |                                     |              |       |     |              |      |   |
| Boiler Room   | Transite Ceiling and Wall Panels    | 500 sq. ft   | Misc. | No  | Fair/Damaged | 1, 6 | Rough edges should be covered or encapsulated. Some areas of broken transite present on walls and ceilings. Area should be priotized for removal. |
| <b>Nash</b>   |                                     |              |       |     |              |      |   |
| <b>First Floor</b>                                    |                                     |              |       |     |              |      |   |
| Student room 10                                       | 9" Floor tile and mastic            | 216 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Student room 11                                       | 9" Floor tile and mastic            | 230 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Student room 12                                       | 9" Floor tile and mastic            | 230 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Student room 13                                       | 9" Floor tile and mastic            | 230 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Student room 14                                       | 9" Floor tile and mastic            | 230 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Student room 15                                       | 9" Floor tile and mastic            | 230 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Student room 16                                       | 9" Floor tile and mastic            | 216 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| First floor cooridor                                  | 9" Floor tile and mastic            | 128 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| <b>Second Floor</b>                                   |                                     |              |       |     |              |      |   |
| Student room 20                                       | 9" Floor tile and mastic            | 170 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Student room 21                                       | 9" Floor tile and mastic            | 121 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Student room 22                                       | 9" Floor tile and mastic            | 121 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Student room 23                                       | 9" Floor tile and mastic            | 121 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Student room 24                                       | 9" Floor tile and mastic            | 121 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Student room 25                                       | 9" Floor tile and mastic            | 121 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Student room 26                                       | 9" Floor tile and mastic            | 170 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Student room 27                                       | 9" Floor tile and mastic            | 216 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |
| Corridor  | 9" Floor tile and mastic            | 500 sq. ft   | Misc. | No  | MNO          | 1, 6 | Covered over with carpet.   |

March 2020

**Assessment Codes** based on 40 CFR Part 763: 1. Damaged or significantly damaged thermal system insulation ACM; 2. Damaged friable surfacing ACM; 3. Significantl friable surfacing ACM; 4. Damaged or significantly damaged friable miscellaneous ACM; 5. ACBM with potential for damage; 6. ACBM with potential for significant d remaining ACM. Please reference AHERA and the school management plan for discussion on assessment codes. MNO means material was not observed during reinspec nonfriable and assessments are not required.