

St. Paul's School: 6-month Surveillance
May 2011


001 - Schoolhouse

Location	ACBM	Approximate Quantity	Category	Friable	Condition November 2009 (3 year)	Condition May 2011	Notes
-----------------	-------------	-----------------------------	-----------------	----------------	--	---------------------------	--------------

Basement							
Basement Ceiling	Pipe Insulation	-----	TSI	Yes	MNO	MNO	Material is located above the plaster ceiling.
Basement Ceiling	Pipe Fittings	-----	TSI	Yes	MNO	MNO	
Electrical Room (017)	9" Floor Tile (black)	20 Sq. Ft.	Misc	No	Fair	MNO	Approximately 160 Sq. Ft. of material removed. Remainder of material is located under electrical switchgear cabinet.
Third Floor							
Room 312 Closet 1	9" Floor Tile (brown/white)	20 Sq. Ft.	Misc	No	Good	N/C	
Room 312 Closet 2	9" Floor Tile (brown/white)	30 Sq. Ft.	Misc	No	Good	N/C	

Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.						
-------------------	---	--	--	--	--	--	--

Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.
Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNO means the material was not observed and further review is required.
Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNO means the material was not observed and further review is required.

Completed By:  Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

002 Payson Science Center

Location	ACBM	Approximate Quantity	Category	Friable	Condition November 2009 (3 year)	Condition May 2011	Notes
----------	------	----------------------	----------	---------	-----------------------------------	--------------------	-------

First Floor							
1st Floor Hall (121)	9" Floor Tile (brown)	320 Sq. Ft.	Misc	No	Fair	Fair	Heavy wear pattern in material near Mechanical Room door.
1st Floor Stairwell #1	9" Floor Tile (brown)	100 Sq. Ft.	Misc	No	Good	N/C	
1st Floor Stairwell #2	9" Floor Tile (brown)	100 Sq. Ft.	Misc	No	Good	N/C	
Second Floor							
2nd Floor Hall/Lobby (220)	9" Floor Tile (brown)	650 Sq. Ft.	Misc	No	Good	N/C	Material observed to be missing 4 tiles and some tiles concealed by walk-off mats taped to floor.
2nd Floor Stairwell #1	9" Floor Tile (brown)	350 Sq. Ft.	Misc	No	Good	N/C	Material observed to be chipped in corner of space.
Classroom/ Lab (212)	Expansion Cloth	5 LF	Misc	No	Good	MNO	

Third Floor							
3rd Floor Hall (318)	9" Floor Tile (brown)	550 Sq. Ft.	Misc	No	Good	N/C	Materials observed to have slight lifting throughout
3rd Floor Stairwell #1	9" Floor Tile (brown)	120 Sq. Ft.	Misc	No	Good	N/C	
3rd Floor Women's Bathroom	9" Floor Tile (black/white)	12 Sq. Ft.	Misc	No	Good	N/C	
Chem Lab (302)	Expansion Cloth	10 LF	Misc	No	Good	MNO	Material originally identified in 1988 survey report.

continued on next page

Chem Lab (304)	Expansion Cloth	10 LF	Misc	No	Good	MNO	Material originally identified in 1988 survey report.
Chem Lab (306)	Expansion Cloth	10 LF	Misc	No	Good	MNO	Material originally identified in 1988 survey report.

Completed By:  Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

002 Payson Science Center

Location	ACBM	Approximate Quantity	Category	Friable	Condition November 2009 (3 year)	Condition May 2011	Notes
Chem Lab (306)	Transite Panels	15 Sq. Ft.	Misc	No	n/a	MNO	Material not tested but assumed ACBM in recent NESHAP survey.
Bio-Chem Lab (309)	Transite Panels	15 Sq. Ft.	Misc	No	n/a	MNO	Material not tested but assumed ACBM in recent NESHAP survey.
Storage / Prep (310)	Expansion Cloth	10 LF	Misc	No	n/a	MNO	Material originally identified in 1988 survey report.
Lab Tech (311)	Expansion Cloth	10 LF	Misc	No	n/a	MNO	Material originally identified in 1988 survey report.
Attic							
Attic Stairwell	9" Floor Tile	100 sq. ft	Misc	No	MNO	MNO	Material has been covered over with rubber stairtreads.
Attic, Vent Hood	Expansion Cloth	10 lf.	Misc	No	Good	N/C	Material located on duct in middle of Fan Room.
Attic, Furne Hood	Chimney Mud	20 Sq. Ft.	TSI	No	Good	N/C	Materials located on three of four chimneys in Fan Room.
Exterior							
All Exterior Windows	Window Glaze	1550 LF	Misc	No	n/a	n/a	Materials tested as part of NESHAP Survey prior to demolition scheduled for late 2011
All Exterior Windows	Window Caulk	1200 LF	Misc	No	n/a	MNO	Materials tested as part of NESHAP Survey prior to demolition scheduled for late 2011
All Exterior Windows	Storm Window Caulk	1000 LF	Misc	No	n/a	MNO	Materials tested as part of NESHAP Survey prior to demolition scheduled for late 2011
Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.						Possible inaccessible ACBM also.

Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.

Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNO means the material was not observed and further review is required.

Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNO means the material was not observed and further review is required.

Completed By:  Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

006 Moore

Location	ACBM	Approximate Quantity	Category	Friable	Condition November 2009 (3 year)	Condition May 2011	Notes
Lower Level							
Janitor Room	9" Floor Tile (tan/brown)	72 Sq. Ft.	Misc	No	Fair	N/C	Material was observed to be lifting with some spot replacement tiles.
Hall by Mech Room	9" Floor Tile (tan/brown)	36 Sq. Ft.	Misc	No	Fair	N/C	Material was observed to be lifting with some spot replacement tiles.
Hall	9" Floor Tile (tan/brown)	105 Sq. Ft.	Misc	No	Fair	N/C	Material was observed to be lifting with some spot replacement tiles.
Stairwells	9" Floor Tile (tan/brown)	196 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with rubber stairreads.
Room 45	9" Floor Tile (tan/brown)	441 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.
Room 46	9" Floor Tile (tan/brown)	441 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.
Room 47	9" Floor Tile (tan/brown)	441 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.
Room 48	9" Floor Tile (tan/brown)	441 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.
Room 49	9" Floor Tile (tan/brown)	441 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.
Office B	9" Floor Tile (tan/brown)	200 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.
Office C	9" Floor Tile (tan/brown)	192 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.

continued on next page

Completed By: _____



Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

006 Moore

Location	ACBM	Approximate Quantity	Category	Friable	Condition November 2009 (3 year)	Condition May 2011	Notes
Upper Level							
Lobby & Entry Vestibule	9" Floor Tile (tan/brown)	484 Sq. Ft.	Misc	No	Fair	N/C	Material on stairs has been covered over with rubber treads.
Room 40	9" Floor Tile (tan/brown)	432 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.
Room 41	9" Floor Tile (tan/brown)	441 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.
Room 42	9" Floor Tile (tan/brown)	432 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.
Room 43	9" Floor Tile (tan/brown)	441 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.
Room 44	9" Floor Tile (tan/brown)	520 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.
Office (113)	9" Floor Tile (tan/brown)	200 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.
Vestibule by Office	9" Floor Tile (tan/brown)	81 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpet.
Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.						Possible inaccessible ACBM also.

Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.
Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNO means the material was not observed and further review is required.
Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNO means the material was not observed and further review is required.

Completed By:  Date: 27 May 11


St. Paul's School: 6-month Surveillance
May 2011

011 Hargate

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
First Floor							
Drafting Room	12" Floor tile (white)	100 sq. ft	Misc.	No	Fair	N/C	Materials were observed to have some lifting throughout.
Corridor	12" Floor tile (white)	300 sq. ft	Misc.	No	Good	N/C	
Drafting Room (045) & Storage (046)							
Second Floor							
North Apartment: Kitchen, Living Room	Transite	40 sq. ft	Misc.	No	Good	MNO	Material is located behind radiator in Study/Living Room.
North Apartment: Kitchen	Floor Tile	150 sq. ft	Misc.	No	MNO	MNO	Materials have been covered over with newer flooring according to the records for the buildings.

Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.						Possible inaccessible ACBM also.
------------	---	--	--	--	--	--	----------------------------------

Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.
Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNO means the material was not observed and further review is required.
Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNO means the material was not observed and further review is required.

Completed By:  Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

013 Oates Music & Dance

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
Music							
Exterior: West Side Music	Corregagate siding	800 sq. ft	Misc	No	Good	N/C	
Dance							
Exterior: North Side	Corregagate siding	1,500 sq. ft	Misc	No	Good	N/C	
Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.						Possible inaccessible ACBM also.

Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.

Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNNO means the material was not observed and further review is required.

Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNNO means the material was not observed and further review is required.

Completed By:  Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

051 New Chapel

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes	
First Floor								
Choir	Flooring Paper	675 sq. ft	Misc	Yes	MNO	MNO	Material is located under the wood Flooring	
Side Entrance near choir	Flooring Paper	100 sq. ft	Misc	Yes	MNO	MNO		
Rectory Hall	Flooring Paper	475 sq. ft	Misc	Yes	MNO	MNO		
Rectory	Flooring Paper	220 sq. ft	Misc	Yes	MNO	MNO		
Side Entrance to Chapel	Transite Board	40 sq. ft	Misc	No	Good	MNO		
Exterior	Other suspect exterior materials are present and further review is required. Prior to any exterior renovation and/or demolition a full NESHAP survey must be conducted in accordance with various state and federal regulations.							Possible inaccessible ACBM also.

Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.

Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNO

Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNO means the material was not observed and further review is required.


Completed By:  Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

055 Memorial Hall

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
Basement							
Women's Dressing Room (023)	9" Floor Tile (black/white)	175 Sq. Ft.	Misc	No	Good	N/C	
	Pipe Insulation	4 Linear Ft.	TSI	Yes	MNO	MNO	Material is located above ductwork.
Theatre Storage (013)	Pipe Insulation	20 Linear Ft.	TSI	Yes	MNO	Good	Material is scheduled for removal in summer 2011.
	Pipe Insulation	50 Sq. Ft.	TSI	Yes	MNO	Good	Material is scheduled for removal in summer 2011.
Mechanical (012)	Duct Skim Coat	6 Linear Ft.	Misc	No	MNO	Good	Material is scheduled for removal in summer 2011.
	Duct Expansion Cloth						
Radio Station (010)	Pipe Insulation		TSI	Yes	MNO	MNO	Material is located above finished ceiling.
	Pipe Fitting Insulation		TSI	Yes	MNO	MNO	
	Duct Skim Coat		TSI	Yes	MNO	MNO	
	Duct Skim Coat		TSI	Yes	MNO	MNO	
Hall and entry to Ladies Room (003)	9" Floor Tile (black/white)	500 sq. ft.	Misc	No	Good	N/C	
Storage (002)	9" Floor Tile (black/white)	80 sq. ft.	Misc	No	Good	N/C	
Pipe Trench thru Rm. 022, 023, 023B, 024, 025, 026, 027, and	Pipe Insulation		TSI	Yes	MNO	Good	Material removed for maintenance except for 30LF which is scheduled to be removed in summer 2011 while steam is shut down.
	Pipe Fitting Insulation		TSI	Yes	MNO	Good	Material removed for maintenance except for 30LF which is scheduled to be removed in summer 2011 while steam is shut down.

Continued on next page.

Completed By: 

Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

055 Memorial Hall

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
First Floor							
Stair hall (103)	9" Floor Tile (brown)	4100 Sq. Ft.	Misc	No	Fair	N/C	Material covered over by carpeting.
Auditorium (104)	9" Floor Tile (brown)	4100 Sq. Ft.	Misc	No	Fair	N/C	Material was observed to have chips and missing tiles present. Some tiles covered over by carpeting.
Mezzanine Level							
Balcony Lobby (202)	9" Floor Tile (black/white)	340 Sq. Ft.	Misc	No	Good	N/C	
North Stairwell (203)	9" Floor Tile (black/white)	28 Sq. Ft.	Misc	No	Good	N/C	
Balcony Level							
Balcony (304)	9" Floor Tile (brown)	2100 Sq. Ft.	Misc	No	Fair	N/C	Material was observed to have chips and missing tiles present.
Auditorium Ceiling	Trowel On Surfacing Material	4880 Sq. Ft.	Surf	Yes	Good	N/C	Material was observed to have small hole in center of ceiling.
Balcony Textured Wall	Trowel On Surfacing Material	360 Sq. Ft.	Surf	Yes	Good	N/C	
Projector Room (303)	Wire Cable Insulation	12 Linear Ft.	Misc	No	Good	N/C	
Attic							
Mechanical Fan Room (401)	Duct Expansion Cloth	40 Linear Ft.	Misc	No	Good	N/C	Materials never tested but assumed to be ACM.

Continued on next page.

Completed By:



Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

055 Memorial Hall

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.						Possible inaccessible ACBM also.

Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.

Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNO means the material was not observed and further review is required.

Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNO means the material was not observed and further review is required.

Completed By:  Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

111 Nash

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
First Floor							
Student Room 10	9" Floor Tile	216 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Student Room 11	9" Floor Tile	231 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Student Room 12	9" Floor Tile	231 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Student Room 13	9" Floor Tile	231 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Student Room 14	9" Floor Tile	231 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Student Room 16	9" Floor Tile	216 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Hallway	9" Floor Tile	128 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Second Floor							
Student Room 20	9" Floor Tile	171 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Student Room 21	9" Floor Tile	121 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Student Room 22	9" Floor Tile	121 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Student Room 23	9" Floor Tile	121 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Student Room 24	9" Floor Tile	121 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Student Room 25	9" Floor Tile	171 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Student Room 26	9" Floor Tile	216 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.

Continued on next page.

Completed By: _____



Date: 27 May 11

**St. Paul's School: 6-month Surveillance
May 2011**

111 Nash

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes

Student Room 27	9" Floor Tile	216 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Hallway	9" Floor Tile	497 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.

Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.						Possible inaccessible ACBM also.
------------	---	--	--	--	--	--	----------------------------------

Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.
Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNO means Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNO means the material was not observed and further review is required.

Completed By:  Date: 27 May 11

**St. Paul's School: 6-month Surveillance
May 2011**

401 Alumni

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
Basement							
Bathroom (011)	9" Floor Tile	18 Sq. Ft.	Misc	No	MNO	MNO	Materials were removed.
First Floor							
Bathroom (104)	Linoleum	36 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with newer flooring.
Business Offices 102, 102B, 116, 119, 120 (previously ASP Office)	Floor Tile	486 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Business Office (107/108)	Floor Tile	486 Sq. Ft.	Misc	No	MNO	MNO	
Human Resources (110/111)	Floor Tile	405 Sq. Ft.	Misc	No	MNO	MNO	
Second Floor							
Bathroom (210) (previously A-1 Bath)	Linoleum	20 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with newer flooring.
Office (217) (previously Office Storage)	Linoleum	16 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.
Hall Closet (227)	Transite floor	10 sq. ft.	Misc	No	Good	N/C	

Continued on next page.

Completed By: _____



Date: 27 May 11

**St. Paul's School: 6-month Surveillance
May 2011**

401 Alumni

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes	
Hall Closet (228)	Transite floor	10 sq. ft	Misc	No	Good	N/C		
Office (219) (previously A-1 Kitchen)	Linoleum	63 Sq. Ft.	Misc	No	MNO	MNO	Material has been covered over with carpeting.	
Third Floor								
Apt. 3, Bath	Linoleum	75 sq. ft	Misc	No	MNO	MNO	Material has been covered over with newer flooring.	
Apt. 4, Bath	Linoleum	75 sq. ft	Misc	No	MNO	MNO		
Apt. 5, Bath	Linoleum	100 sq. ft	Misc	No	MNO	MNO		
Hall Closet (306)	Transite floor	10 sq. ft	Misc	No	MNO	MNO	Material assumed to be under carpeting.	
Hall Closet (314)	Transite floor	10 sq. ft	Misc	No	MNO	Good		
Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.						Possible inaccessible ACBM also.	

Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.

Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNO means the material was not observed and further review is required.

Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNO means the material was not observed and further review is required.

Completed By:



Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

402 Scudder House

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes

Basement							
Basement	Pipe Insulation	632 lf	TSI	Yes	MNO	MNO	Materials were removed by ABS during summer of 2009.
	Pipe Fitting Insulation	79 observed	TSI	Yes	MNO	MNO	

Second Floor							
Bathroom	9" Floor Tile	75 Sq. Ft.	Misc.	No	Good	N/C	Prior to removal, testing is recommended.

Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.						Possible inaccessible ACBM also.
------------	---	--	--	--	--	--	----------------------------------

Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.
Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNO means the material was not observed and further review is required.
Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNO means the material was not observed and further review is required.

Completed By:  Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

403 Red Barn

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
-----------------	-------------	-----------------------------	-----------------	----------------	--	---------------------------	--------------

First Floor

Mishop	Transite Ceiling Panel	600 sq. ft	Misc.	No	Good	N/C	Material observed to have a 3/4" hole in center of ceiling.
---------------	-------------------------------	-------------------	--------------	-----------	-------------	------------	--

Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.						Possible inaccessible ACBM also.
-------------------	---	--	--	--	--	--	---

Category: MISC is miscellaneous material, ISI is thermal system insulation, SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.

Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNO means the material was not observed and further review is required.

Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNO means the material was not observed and further review is required.

Completed By:

Date: 27 May/11

**St. Paul's School: 6-month Surveillance
May 2011**

404 Central Heating Plant

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
Facilities Offices First Floor							
Office (104 & 105) (previously Facilities Director's Office)	Pipe Insulation	-----	TSI	Yes	MNO	MNO	Material may be above drop ceiling or within wall space.
	Pipe Fitting Insulation	-----	TSI	Yes	MNO	MNO	Material may be above drop ceiling or within wall space.
Offices (103) (previously maintenance & secretaries office)	Pipe Insulation	-----	TSI	Yes	MNO	MNO	Material may be above drop ceiling or within wall space.
	Pipe Fitting Insulation	-----	TSI	Yes	MNO	MNO	Material may be above drop ceiling or within wall space.
Offices (106,107, & 108) (previously maintenance & secretaries office)	Pipe Insulation	-----	TSI	Yes	MNO	MNO	Material may be above drop ceiling or within wall space.
	Pipe Fitting Insulation	-----	TSI	Yes	MNO	MNO	Material may be above drop ceiling or within wall space.
Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.						Possible inaccessible ACBM also.

Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.

Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNO means the material was not observed and further review is required.

Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNO means the material was not observed and further review is required.

Completed By: _____



Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

406 Post Office

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
----------	------	----------------------	----------	---------	---------------------------------	--------------------	-------

First Floor							
Post Master Area	9" Floor Tile and associated mastic	690 sq. ft	Misc.	No	Good	N/C	Approximately 60 sq. ft of material was removed for a new bathroom by Seacoast Diversified in 2004.
Post Master Area	Trowelled-On Surfacing Material	1,477 sq. ft	Misc.	Yes	Good	N/C	

Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.						Possible inaccessible ACBM also.
------------	---	--	--	--	--	--	----------------------------------

Category: MISC is miscellaneous material, ISI is thermal system insulation, SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.

Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNO means the material was not observed and further review is required.

Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNO means the material was not observed and further review is required.

Completed By:  Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

411 Service Building (White Farm/Shipping & Receiving)

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
-----------------	-------------	-----------------------------	-----------------	----------------	--	---------------------------	--------------

Basement Level							
Boiler Room	Transite Ceiling and Wall Panels	500 sq. ft	Misc.	No	Damaged	N/C	Rough edges should be covered or encapsulated. Broken panels and loose pieces removed June 2010.

Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.	Possible inaccessible ACBM also.
-------------------	--	---

Category: MISC is miscellaneous material. TSI is thermal system insulation. SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.

Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). M/N/O means the material was not observed and further review is required.

Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. M/N/O means the material was not observed and further review is required.

Completed By:  Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

414 Food Services

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
----------	------	----------------------	----------	---------	---------------------------------	--------------------	-------

Basement							
Crawlspace	Pipe Fittings	-----	TSI	Yes	MNO	MNO	
First Floor							
Common Room	Flooring Paper	1,700 sq. ft	Misc.	Yes	MNO	MNO	Material is under wood flooring.
Upper Dining Room	Flooring Paper	3,500 sq. ft	Misc.	Yes	MNO	MNO	Material is under wood flooring.

Second Floor							
Food Service's Storage Rooms	Flooring Paper	240 sq. ft	Misc.	Yes	MNO	MNO	Material is under wood flooring which has been covered by 12" tiles in half of room.
Men's Locker Room	Flooring Paper	200 sq. ft	Misc.	Yes	MNO	MNO	Material is under wood flooring which has been covered by 12" tiles.
Men's Restroom	Flooring Paper	60 sq. ft	Misc.	Yes	MNO	MNO	Material is under wood flooring which has been covered by 12" tiles.
Women's Locker Room	Flooring Paper	160 sq. ft	Misc.	MNO	MNO	MNO	Material is under wood flooring which has been covered by carpet.
Women's Restroom	Flooring Paper	80 sq. ft	Misc.	Yes	MNO	MNO	Material is under wood flooring which has been covered by 12" tiles.
Breakroom	Flooring Paper	225 sq. ft	Misc.	Yes	MNO	MNO	Material is under wood flooring which has been covered by carpet.
	Linoleum	225 sq. ft	Misc.	No	n/a	MNO	Material is covered by carpet.
	Flooring Paper	225 sq. ft	Misc.	Yes	MNO	MNO	Material is under wood flooring which has been covered by linoleum.
Linoleum Storage	Linoleum	225 sq. ft	Misc.	No	n/a	Poor	Material is lifting and tearing.
Corridor	Flooring Paper	100 sq. ft	Misc.	Yes	MNO	MNO	Material is under wood flooring which has been covered half by carpet and half by 12" tiles.

continued on next page

Completed By:  Date: 27 May 11

St. Paul's School: 6-month Surveillance
May 2011

414 Food Services

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
Third Floor							
Guest Bath	Flooring Paper	130 sq. ft	Misc.	Yes	MNO	MNO	Material is under wood flooring which has been covered by 12" tiles.
Resident Bath	Flooring Paper	60 sq. ft	Misc.	Yes	MNO	MNO	Material is under wood flooring which has been covered by newer vinyl flooring.
Corridor	Flooring Paper	360 sq. ft	Misc.	Yes	MNO	MNO	Material is under wood flooring which has been covered by carpet.
Fourth Floor							
Room 16	Flooring Paper	120 sq. ft	Misc.	Yes	n/a	MNO	Material is under wood flooring.
Room 17	Flooring Paper	110 sq. ft	Misc.	Yes	n/a	MNO	Material is under wood flooring.
Room 18	Flooring Paper	160 sq. ft	Misc.	Yes	n/a	MNO	Material is under wood flooring.
Linen Closet	Flooring Paper	50 sq. ft	Misc.	Yes	n/a	MNO	Material is under wood flooring.
Room 19	Flooring Paper	160 sq. ft	Misc.	Yes	n/a	MNO	Material is under wood flooring.
Room 20	Flooring Paper	140 sq. ft	Misc.	Yes	n/a	MNO	Material is under wood flooring.
Storage by Rm 20 & 21	Flooring Paper	16 sq. ft	Misc.	Yes	n/a	MNO	Material is under wood flooring.
Room 21	Flooring Paper	200 sq. ft	Misc.	Yes	n/a	MNO	Material is under wood flooring.
Corridor	Flooring Paper	300 sq. ft	Misc.	Yes	n/a	MNO	Material is under wood flooring.

continued on next page

Completed By: 

Date: 27 May 11

**St. Paul's School: 6-month Surveillance
May 2011**

414 Food Services

Location	ACBM	Approximate Quantity	Category	Friable	Condition October 2009 (3 year)	Condition May 2011	Notes
Throughout	Other suspect ACBM is present in and on the building that requires further review, testing, assessment and, based on the results modifications to the management plan may be required. In addition, interior and exterior inspection are required prior to any renovation or demolition work.						Possible inaccessible ACBM also.

Category: MISC is miscellaneous material; TSI is thermal system insulation; SURF is surfacing material. Categorized in accordance with 40 CFR Part 763.

Friable: Yes means that when dry, it can be easily crumbled or pulverized to powder by hand (ceiling tiles, plaster, pipe insulation, etc.). No means it is nonfriable (floor tiles, etc.). MNO means the material was not observed and further review is required.

Condition: N/C means no change was observed. N/A means no access was gained during the reinspection. MNO means the material was not observed and further review is required.

Completed By:

Date: 27 May 11